

Traveler Title:

Booster Correction Multipole Magnet Assembly

Specification No:

5520-TR-333819

Revision:

I

DR No:

4491

Step No:

7.10

Drawing No:

5520-ME-445004

Routing Form No:

Serial No:

BMA050

Rework ID:

0

Discrepancy Description:

Traveler instructs to, perform an electrical test.
 DC resistance limit for the Skew Quad circuit is 1300 to 1400 milli ohms actual measured resistance is 1209 milli ohms.

Originator:

Dennis Gaw

Date:

3/4/2008 3:18:24 PM

Cause of Nonconformance:

Of the eight type C1 coils installed in this magnet, five of them have the layer 5 (skew quad) conductor with a lower resistance: C1-377, 380, 385, 386, 387. On average each of these has a resistance about 30 mohm less than the typical coil, so we would expect this circuit to be 150 mohm less than the typical magnet. Measurement confirms this to be the case. The lower resistance of these layers is due to the use of a different conductor.

Responsible Authority:

Jamie Blowers

Date:

3/4/2008 3:18:24 PM

Disposition:

If the inductance is within our tolerances, use the coil as is.
Disposition verify notes: The is inductance is within the limits specified in the traveler.

Responsible Authority:

Sasha Makarov

Date:

3/5/2008 3:47:37 PM

Corrective Action to Prevent Recurrence:

None
Disposition verify notes: none.

Responsible Authority:

Sasha Makarov

Date:

3/5/2008 3:47:37 PM

Corrective Action/Disposition Verified By:

Dennis Gaw

Date:

3/6/2008 10:43:00 AM

Will Configuration be affected?: YES NO

Identified problem area:

- Material Manpower Method Machine Measurement

Reviewed By:

Bob Jensen

Date:

3/6/2008 2:16:18 PM