

Traveler Title:

Main Injector Kickers and Extraction Pulse Forming Line
Assy w/Cable

Specification No:

333927

Revision:

None

DR No:

4636

Step No:

3.1.8, 8.4

Drawing No:

359554

Routing Form No:

Serial No:

PFLB003

Rework ID:

0

Discrepancy Description:

The cable length is outside of provided limit. See traveler for details.

Originator:

Jan Szal

Date:

2/27/2009 7:48:50 AM

Cause of Nonconformance:

Cable Length is longer than limits in Traveler/Dwg.

Responsible Authority:

Bob Jensen

Date:

3/26/2009 3:45:07 PM

Disposition:

TRR 2044 was drawn and Traveler updated to a Rev A on 2/23/2009 changing limits from 560 +10/-0 ft to 560 minimum.

Responsible Authority:

Bob Jensen

Date:

3/26/2009

Corrective Action to Prevent Recurrence:

None. Traveler Updated to correct issue.

Responsible Authority:

Bob Jensen

Date:

3/26/2009

Corrective Action/Disposition Verified By:

Bob Jensen

Date:

3/26/2009 3:47:47 PM

Will Configuration be affected?: YES NO

Identified problem area:

- Material Manpower Method Machine Measurement

Reviewed By:

Bob Jensen

Date:

3/26/2009