

**Traveler Title:**

BMA Full Magnet Impregnation

**Specification No:**

5520-TR-333859

**Revision:**

None

**DR No:**

4466

**Step No:**

14.14

**Drawing No:**

5520-ME-445311

**Routing Form No:**

**Serial No:**

BMA031

**Rework ID:**

0

**Discrepancy Description:**

Visual inspection discovered that coil turns with exposed copper are not covered with the potting epoxy.  
See the digital images.

**Originator:**

Dennis Gaw

**Date:**

12/10/2007 2:01:53 PM

**Cause of Nonconformance:**

not known

**Responsible Authority:**

Dennis Gaw

**Date:**

12/10/2007 2:01:53 PM

**Disposition:**

**Responsible Authority:**

**Date:**

**Corrective Action to Prevent Recurrence:**

**Responsible Authority:**

**Date:**

---

**Corrective Action/Disposition Verified By:**

**Date:**

**Will Configuration be affected?:**     YES     NO

---

**Identified problem area:**

Material       Manpower       Method       Machine       Measurement

**Reviewed By:**

**Date:**