TD/Q&M JB 14888

INV POSTED

Additional Parts Request

Serial #	EDBC042	Requested by (include ID)	S. Baketz (15714)
Date	8/19/2013	Need by date	8/21/2013
Project/Task #	30/30.9.5.2.7.1.1.1	Deliver to	IB#2
Job Ticket #	406	MMR #	
PO #		Machine Shop Req #	
Other	EPB to EDBC conversion		

☐ Defective Parts Issued ☐ Parts Scrapped ☐ A/R Items
☐ Defective Assembly ☐ Missing from Kit already issued
☑ Individual Parts ☐ Consumables ☐ Parts Lost

Acquisitioner Name/ID Marsha Schmidt

Date 8/19/13

	Location	Part #	Rev.	QTY	UOM	Description	RF #	Stock
1)	18A7	MB 351973		1	ea	Tube #1 (R.E)	95921	4
2)	18A8	MB 351974		1	ea	Tube #2 (R.E)	95922	4
3)	18A8	MB 351975		1	ea	Tube #3 (R.E)	95923	4
4)	15B6	MA 351140		3	ea	Rod Copper .50 Dia. (L.E.)	66097	33
5)	15B3	MA 351127	A	6	ea	Tube Copper (3/8" OD X 1.09"Lg)	66290	200
6)	15B7	MA 351143		8	ea	Reducing Tee (L.E.)	95817	17
7)	R1,3,4	MB 351980		1	ea	Connecting Bus L.H.	93931	2
8)	18B2	MA 351981		1	ea	Connecting Bus R.H.	93929	2
9)	R2,S2,L3 LB1	MA 445442		8	ea	SHCS #10-24 X .500" Lg	90640	64
10)	15D2	MC 351215		4	ea	Beam Tube-Coil Insulator	66263	191

Additional Parts Request

Serial #	EDBC042	Requested by (include ID)	S. Baketz (15714)
Date	8/19/13	Need by date	8/21/13
Project/Task #	30/30.9.5.2.7.1.1.1	Deliver to	IB#2
Job Ticket #	406	MMR #	
PO #		Machine Shop Req #	
Other	EPB to EDBC conversion		

☐ Defective Parts Issued ☐ Parts Scrapped ☐ A/R Items
☐ Defective Assembly ☐ Missing from Kit already issued
☑ Individual Parts ☐ Consumables ☐ Parts Lost

Acquisitioner Name/ID Marsha Schmidt
Date 8/19/13

	Location	Part #	Rev.	QTY	UOM	Description	RF #	Stock
11)	6C8	MC 351978		1	ea	Manifold Support (R.E.)	93932	2
12)	R1,1,3	MB 351293		4	ea	Power Flag Support Block (R.E.)	95836	14
13)	R1,3,1	MC 351979		2	ea	Power Flag – Return End	95837	8
14)	T12,3	MC 351616		1	ea	Power Flag – Right Hand	69396	11
15)	T12,3	MC 351617		1	ea	Power Flag – Left Hand	69397	11
16)	8A2	MA 318682		6	ea	SHCS 1/4-20 X 1"	93875	84
17)	8A4	MA 318689	C	6	ea	Washer, Flat 1/4" Dia. SS (R.E)	62823	1734
18)	23D8	MA 393315		8	ea	Washer, Flat 1/2" Dia. SS	81382	80
19)	10A4	331458	A	~~8~~ 2	ea	HHCS 1/2-13 X 3.50"Lg SS	75357	2
20)	1D3	MA 125281		2	ea	Vinyl Plastic Flange Cover	97388	55
21)	20A5	MC 388059		1	ea	4" Vac Coupling Flange	90833	22

Additional Parts Request

Serial #	EDBC042	Requested by (include ID)	S. Baketz (15714)
Date	8/19/13	Need by date	8/21/13
Project/Task #	30/30.9.5.2.7.1.1.1	Deliver to	IB#2
Job Ticket #	406	MMR #	
PO #		Machine Shop Req #	
Other	EPB to EDBC conversion		

☐ Defective Parts Issued ☐ Parts Scrapped ☐ A/R Items
☐ Defective Assembly ☐ Missing from Kit already issued
☑ Individual Parts ☐ Consumables ☐ Parts Lost

Acquisitioner Name/ID Marsha Schmidt
Date 8/19/13

	Location	Part #	Rev.	QTY	UOM	Description	RF #	Stock	
22)	20B4	MA 388119		4	ea	Beam Tube Retainer	75443	44	
23)	R1,2,3	MD 445429	A	2	ea	Pipe Assy	89591	6	
24)	R2,1,2	MC 351294	A	1	ea	Support Block (L.E.)	69682	11	
25)	R1,3,2	MB 445430		2	ea	Clamp Block (L.E.)	92281	9	
26)	7C4	MB 445432	A	9	ea	Peek Tube	89504	29	
27)	21B1	MA 445440		8	ea	Elbow Compression Tube Fitting	92235	16	
28)	R1,1,3	MB 445436		8	ea	Copper Tube	89533	176	
29)	20D4	MA 445441		2	ea	Compression Tube Fitting	92225	15	
30)	17C2	MC 388057	A	1	ea	Adapter – 4" Bellows to Vac Tube	90998	18	
31)	R7,3,3	MC 388058	A	1	ea	4" Bellows	80031	62	61 SP11-000600

STOCKROOM SIGNATURE ID# 14888 DATE 8/21/13
PARTS RECEIVED BY Shirley Baketz ID# 15714 DATE 8/21/13
PARTS DELETED FROM DATABASE SJB ID# 14888 DATE 9/3/13