B9S-AES-003 - no caps Full Spectrum

5 December 2014 - MP9 Furnace



During the N2 bleed the RGA isolation valve closed, but the RGA stayed on. The RGA has been reading the vacuum where there was not active pumping. Once the RGA isolation valve was opened again, it took a while to pump out all the gases.
This explain the 'bad' spectrum at the end of the 800C bake