

ADDITIONAL PARTS REQUEST

Serial # RQN001/RQN002 Requested by (include ID) B. Jensen 0315
 Date 1/26/2011 Need by date 1/28/2011
 Project/Task # M&S 425/2.0.1.1.1.4 Deliver to IB#2
 Job Ticket # 471 MMR # _____
 PO # _____ Machine Shop Req # _____
 Other RQN Magnet Assembly

<input type="checkbox"/> Defective Parts Issued	<input type="checkbox"/> Parts Scrapped	<input type="checkbox"/> A/R Items
<input type="checkbox"/> Defective Assembly	<input checked="" type="checkbox"/> Missing from Kit already issued	
<input checked="" type="checkbox"/> Individual Parts	<input type="checkbox"/> Consumables	<input type="checkbox"/> Parts Lost
Acquisitioner Name/ID <u>Alley 4698</u>		Date <u>1-26-11</u>

	Location	Part #	Rev.	QTY	UOM	Description	RF #	Spares #
1)	R10,S1,L	338227	A	4	ea	Flux Return End Plate	65746	44 STK (22)
2)	_____	_____	_____	_____	_____	_____	_____	_____
3)	_____	_____	_____	_____	_____	_____	_____	_____
4)	_____	_____	_____	_____	_____	_____	_____	_____
5)	_____	_____	_____	_____	_____	_____	_____	_____
6)	_____	_____	_____	_____	_____	_____	_____	_____
7)	_____	_____	_____	_____	_____	_____	_____	_____
8)	_____	_____	_____	_____	_____	_____	_____	_____
9)	_____	_____	_____	_____	_____	_____	_____	_____
10)	_____	_____	_____	_____	_____	_____	_____	_____

NOTE: 2 pcs = 1
RE PACKAGE AS SUCH
DO ~~NOT~~ TDI NV

STOCKROOM SIGNATURE [Signature] ID# 14803 DATE 1/31/11
 PARTS RECEIVED BY [Signature] ID# 0315 DATE 1/31/2011
 PARTS DELETED FROM DATABASE _____ ID# _____ DATE _____